Title:

POWER SYSTEM INITIALIZATION DURING PDS

Models:

'06 Applicable Toyota & Scion

ഗ Ш

TSB REVISION NOTICE:

BULLETIN

March 1, 2006

 March 8, 2006: The Power System Initialization Table has been updated to include TSB references for the back door power window for Sequoia, the compass for Solora, and the power window for Prius.

Previous versions of this TSB should be discarded.

Introduction

The following is a list of the vehicle systems (Power Window, Sliding Roof, Tire Pressure Warning System, etc.) that need initialization during Pre-Delivery Service (PDS) and the TSB numbers containing details on initializing each specific system.

NOTE:

Items in RED also need to be initialized any time the battery has been disconnected.

Applicable Vehicles

2006 model year Applicable Toyota and Scion vehicles listed in the following table.

Power System Initialization **Table**

MODEL NAME	INITIALIZATION SYSTEM ITEMS									
	BACK DOOR POWER WINDOW	COMPASS	POWER WINDOW	POWER BACK DOOR	POWER SLIDING DOOR	SLIDING ROOF	TIRE PRESSURE WARNING SYSTEM			
							DIRECT	INDIRECT		
4Runner	PG021-02	PG016-02	PG018-02	-	-	PG018-02	PD007-03	-		
Avalon	-	PD051-05	PD050-05	-	-	PD049-05	-	-		
Camry	-	PG008-01	-	-	-	PG015-01	-	-		
Corolla	-	PG005-02	-	-	=	-	-	PD024-04		
Highlander	-	PD037-05	-	-	=	-	-	PD039-05		
Highlander HV	-	PD013-05	-	-	=	-	-	=		
Land Cruiser	-	PG018-00	-	-	-	-	PD019-05	-		
Matrix	-	PG006-02	-	-	-	-	-	PD025-04		
Prius	-	-	PD010-03	-	-	-	PD084-05	-		
RAV4	-	-	-	-	=	-	PD090-05	=		
Sequoia	PD007-05	PG021-00	-	-	=	-	PD034-04	=		
Sienna	-	PD072-05	PD071-05	PD068-05	PD067-05	PD069-05	-	PD073-05		
Solara	-	PD006-03	PD006-03	-	=	PD006-03	-	PD006-03		
Tacoma	-	PD060-05	-	-	=	-	PD062-05	-		
Tundra	-	PD013-03	-	-	=	-	PD035-04	-		
Scion tC	-	-	PD021-05	-	=	PD020-05	-	PD026-05		

Warrantv Information

OP CODE	DESCRIPTION		OFP	T1	T2
N/A	Not Applicable to Warranty	_	ı	-	-

