



**Technical Service  
BULLETIN**

July 7, 2006

Title:

**M.I.L. "ON" DTC P0AA6 OR P3009,  
INFORMATION CODES 526 & 613**

Models:

'04 – '06 Prius

**ENGINE  
EG045-06**

**Introduction** Some customers with 2004 to 2006 model year Prius vehicles may experience a M.I.L. "ON" condition with DTC P0AA6 or P3009 with information codes 526 and 613. The transaxle assembly has been improved to prevent this condition.

**NOTE:**

This TSB applies **ONLY** if **BOTH** information codes 526 **AND** 613 are present.

**Applicable  
Vehicles**

- **2004 – 2005** model year **Prius** vehicles.
- **2006** model year **Prius** vehicles produced **BEFORE** the Production Change Effective VINs shown below.

**Production  
Change  
Information**

MODEL	PLANT	PRODUCTION CHANGE EFFECTIVE VIN*
Prius	Tsutsumi	JTDKB2#U# <u>63</u> 164850
	Toyota Auto Body	JTDKB2#U# <u>67</u> 072340

\* Underlined number in VIN (11th digit) represents assembly plant line code.

**Parts  
Information**

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
30900-47040	Same	HV Transaxle Assembly	1
00272-SLLC2	Same	Super Long Life Coolant (SLLC)	1
08886-02305	Same	ATF WS	

**Warranty  
Information**

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
EG5033	R & R Hybrid Vehicle Transaxle Assembly	5.9	30900-47040	8A	99
Combo A	Connection of Toyota Diagnostic Tester	0.2			



**Applicable Warranty\*\*:**

This repair is covered under the Toyota Hybrid Vehicle System Component Warranty. This warranty is in effect for 60 months or 60,000 miles, whichever occurs first, from the vehicle's in-service date.

\*\* Warranty application is limited to correction of a problem based upon a customer's specific complaint.



Required  
SSTs

ITEM NO.	SPECIAL SERVICE TOOLS (SSTs)	PART NUMBER	QTY	DRW**
1	<b>Toyota Diagnostic Tester Kit*</b> NOTE: <ul style="list-style-type: none"> <li>All components from this kit/set are required.</li> <li>12 Megabyte Diagnostic Tester Program Card (P/N 01002593–005) with version 13.3a Software (or later) is required.</li> </ul> 	TOY220036	1	9
2	<b>CAN Interface Module Kit*</b> NOTE: <ul style="list-style-type: none"> <li>All components from this kit/set are required.</li> </ul> 	01002744	1	9

\* Essential SSTs.

\*\* Refers to drawer number in SST Storage System.

**NOTE:**

**Additional Diagnostic Tester Kits, CAN Interface Modules, Program Cards, or other SSTs may be ordered by calling SPX/OTC at 1-800-933-8335.**

Repair  
Procedure

Remove and replace the hybrid vehicle transaxle assembly.

Refer to the Technical Information System (TIS):

- 2004 or 2005 model year Prius Repair Manual: *Hybrid Transaxle: Hybrid Vehicle Transaxle Assy: Replacement*
- 2006 model year Prius Repair Manual: *Hybrid Transmission / Transaxle: Hybrid Vehicle Transaxle Assembly Removal and Installation*